



B1	L1	L2	A	B2	D1	D2	a1	b1	t1	t2	R
16	20	20	22	45	6,8	M8	11	30	11,5	12	8
	20	40	22	45	6,8	M8	11	30	11,5	12	8
30	26	40	35	60	6,8	M8	17,5	46	19,5	20	10
	26	63	35	60	6,8	M8	17,5	46	19,5	20	10
48	36	32	46	100	10,3	M12	23	74	25,5	26	12,5
	36	50	46	100	10,3	M12	23	74	25,5	26	12,5
	36	63	46	100	10,3	M12	23	74	25,5	26	12,5
	36	80	46	100	10,3	M12	23	74	25,5	26	12,5
77	56	50	60	150	14	M16	30	114	35,5	36	16
	56	71	60	150	14	M16	30	114	35,5	36	16
	56	100	60	150	14	M16	30	114	35,5	36	16